

Obsolete Parts

EMRI A/S
Marielundvej 37A
DK-2730 Herlev
Denmark

Tel: +45 4491 8204
www.emri.dk

Document: EMRI User Doc Template.docx
Updated: 04-03-2024

Category	Obsolete part	Replaced by	Notes
Autopilot	SEM1000	SEM300/FAP-3000	
Autopilot	SEM200	SEM300/FAP-3000	
Autopilot	FAP-2000	SEM300/FAP-3000	
Indicator	RIB71	RIB71X	New unit has a better readable scale.
Indicator	RIB711-RG	RIB71X	
Indicator	RIB51	RIB51X	New unit has a better readable scale.
Indicator	RIB511-RG	RIB51X	
Indicator	RIA411	RIA51X	
Indicator	RIA511	RIA51X	
Indicator	RIA711	RIA71X	
Indicator	MIB180	MIB180X	
Indicator	SSD	DIB10	
Indicator	ROT144-30-C	ROT144-30-CX	
Indicator	ROT144-60-C	ROT144-60-CX	
Indicator	TPP (all types)	TPL	
Indicator	RIS	SAB	
Servo Unit	RSM (Older types)	Contact EMRI	Spare parts for some older types of RSM servos are not available. Contact EMRI for alternatives.
Amplifier	PR5111-4-5466	PR4104-4-5466KIT	
Amplifier	PR5111-4-5467	PR4104-4-5467KIT	
Amplifier	PR5111-4-5468	PR4116-4-5468KIT	
Amplifier	PR5111-4-5469	PR4104-4-5469KIT	
Amplifier	PR5111-4-5786	PR4104-4-5786KIT	

Monitor/PC	MPC11	MPC12	
Monitor/PC	MPC21	MPC-XXX	Contact EMRI for clarification.
Monitor/PC	JH15T05	JH15T17	
Monitor/PC	JH15T15	JH15T17	
PLC Modules	CQM1-CPU21	Upgrade needed	Contact EMRI for instructions. View section WMS/PLC upgrade.
PLC Modules	CQM1H-CPU21	Upgrade needed	Contact EMRI for instructions. View section WMS/PLC upgrade.
PLC Modules	CQM1-ID212	Upgrade needed	Contact EMRI for instructions. View section WMS/PLC upgrade.
PLC Modules	CQM1-OC221	Upgrade needed	Contact EMRI for instructions. View section WMS/PLC upgrade.
PLC Modules	CQM1-PA206	Upgrade needed	Contact EMRI for instructions. View section WMS/PLC upgrade.
PLC Modules	G71-OD16 24DC	Upgrade needed	Contact EMRI for instructions. View section WMS/PLC upgrade.

Note: ALL types of Omron CQM1 and G71 PLC modules are obsolete. Not all types are listed here.