

Obsolete Parts

EMRI A/S Meterbuen 27C DK-2740 Skovlunde Denmark

TEL.: +45 44918204

www.emri.dk

Document: EMRI Obsolete Parts.docx

Updated: 16-01-2025



Category	Obsolete part	Replaced by	Notes
Autopilot	SEM1000	SEM300/FAP-3000	
Autopilot	SEM200	SEM300/FAP-3000	
Autopilot	FAP-2000	SEM300/FAP-3000	
Indicator	RIB71	RIB71X	New unit has a better readable scale.
Indicator	RIB711-RG	RIB71X	
Indicator	RIB51	RIB51X	New unit has a better readable scale.
Indicator	RIB511-RG	RIB51X	
Indicator	RIA411	RIA51X	
Indicator	RIA511	RIA51X	
Indicator	RIA711	RIA71X	
Indicator	MIB180	MIB180X	
Indicator	SSD	DIB10	
Indicator	ROT144-30-C	ROT144-30-CX	
Indicator	ROT144-60-C	ROT144-60-CX	
Indicator	TPP (all types)	TPL	
Indicator	RIS	SAB	
Servo Unit	RSM (Older types)	Contact EMRI	Spare parts for some older types of RSM servos are not available. Contact EMRI for alternatives.
Servo Unit	RSM621-I47	Upgrade needed	
Servo Unit	RSM721-230-110DC	Upgrade needed	
Servo Unit	RSM721-440-110DC	Upgrade needed	
Servo Unit	RSM721-440-MOS	Upgrade needed	



Servo Unit	RSM721-440-24VDC	Upgrade needed	
Servo Unit	RSM721-440-24DC	Upgrade needed	
Servo Unit	RSM721-440-DC1	Upgrade needed	
Amplifier	PR5111-4-5466	PR4104-4-5466KIT	
Amplifier	PR5111-4-5467	PR4104-4-5467KIT	
Amplifier	PR5111-4-5468	PR4116-4-5468KIT	
Amplifier	PR5111-4-5469	PR4104-4-5469KIT	
Amplifier	PR5111-4-5786	PR4104-4-5786KIT	
Monitor/PC	MPC11	MPC12	
Monitor/PC	MPC21	MPC-XXX	Contact EMRI for clarification.
Monitor/PC	JH15T05	JH15T17	
Monitor/PC	JH15T15	JH15T17	
WMS	WMS624-4	Upgrade needed	
WMS	WMS62	Upgrade needed	
WMS	WMS52-186	Upgrade needed	
WMS	WMS92	Upgrade needed	
PLC Modules	CQM1-CPU21	Upgrade needed	Contact EMRI for instructions.
PLC Modules	CQM1H-CPU21	Upgrade needed	Contact EMRI for instructions.
PLC Modules	CQM1-ID212	Upgrade needed	Contact EMRI for instructions.
PLC Modules	CQM1-OC221	Upgrade needed	Contact EMRI for instructions.
PLC Modules	CQM1-PA206	Upgrade needed	Contact EMRI for instructions.
PLC Modules	G71-OD16 24DC	Upgrade needed	Contact EMRI for instructions.

Note: ALL types of Omron CQM1 and G71 PLC modules are obsolete. Not all types are listed here.